

RTS INC.

Material Safety Data Sheet Bare Essentials

Section 1. Chemical Product and Company Identification

Product Name/Trade Name	BARE ESSENTIALS
Manufacturer:	RTS INC. 5195 Bradco Blvd MISSISSAUGA ON 2A6 Tel: 905 625 5552 Date: April 4, 2013

Section 2 Hazardous Ingredients

Name	%	CAS#	LD50/LC50
Sodium Alkyl Ether Sulphate	3-7	68585-34-2	NAv
Cocoamidopropyl Betaine	1-3	70851-07-9	>5000mg/kg(rat oral)

Section 3 Physical Data

State	Liquid-viscous	pH	7-8
Appearance	silver pearl	% Volatile	Approx 90%
Odor	Mild Fruity	Boiling Point	Approx. 100C.
Specific Gravity	1.02-1.03	Vapor Pressure	N Av.
Solubility	100% in water		

Section 4 Fire & Explosion

Flammable: YES	NO	X
Means of Extinction:	Water, Carbon Dioxide, Dry Chemical or Foam	
Special Procedures:	Fire Fighters should wear self-contained breathing apparatus.	
Flash Point: & Method:	> 95°C TCC	
Hazardous Combustion Products:	N/A	

Section 5 Reactivity Data

Chemical Stability: YES	X	NO
Conditions:	N Ap	
Incompatibility: YES	NO	X
What Substances:		
Reactivity / Conditions:	Not Applicable	
Hazardous Decomposition Products:	None.	

Section 6 Toxicological Properties

Route of Entry *Bare Essentials*

Skin Contact	Skin Absorption	Eye Contact	X
Inhalation Acute	Inhalation Chronic	Ingestion	X
Effects of Acute Exposure: Contact may irritate the eyes. Mild irritation if swallowed			
Effects of chronic exposure: Prolonged and repeated contact with skin may cause irritation			
Carcinogenicity; Reproductive Effects; Teratogenicity; Mutagenicity: No evidence of effects			

Section 7 Preventative Measures

Protective Equipment

Gloves: Not normally required

Eyes: Not normally required

Respiratory: Not normally required

Footwear: Not Applicable

LEAK AND SPILL PROCEDURE: For small spills wipe up or mop up. For large spills control spill with absorbent; transfer to non-leaking containers. Rinse area thoroughly

WASTE DISPOSAL: Reclaim or dispose in accordance with local regulations

STORAGE REQUIREMENTS: Store in cool, dry and well-ventilated area

Section 8 First Aid Measures

Skin: Wash with soap and water for 15 minutes.

Eyes: Remove contact lenses Flush eyes with cool running water holding eyelids apart to ensure thorough rinsing for 15 minutes.

Inhalation: Move to fresh air and restore breathing, if required.

Ingestion Drink large amounts of water or milk. Do not give anything by mouth to a convulsing or unconscious person. See a doctor immediately.

General Advice: If irritation persists see a doctor immediately.

Section 9 Preparation Information

Transportation: Not regulated

WHMIS: Not Regulated

Prepared by: RTS Inc. Quality Assurance Department

Emergency Telephone Number: 613 996 6666 (CANUTEC)

Date: April 4, 2013